

# Notice



CORRECTION  
 SERVICE FLASH

PRODUCTION CHANGE  
 ADD INFORMATION

FILE NO.

Please add this notice to the Service Manual listed below.

Category: COLOR TELEVISION

Date: FEBRUARY / 07 / 2012

Model: DP42740

Effective from : Chassis No. P42740-05

Destination: U.S.A. / CANADA

REF : No. SM780190-05

**NOTE:** Match the Chassis No. on the unit's back cover with the Chassis No. in the Service Manual. **If the Service Manual Chassis No. does not match the unit's**, additional Service Literature is required. This chassis is similar to Chassis No. P42740-04. Only the **difference** Service Information is given in this manual. For detailed Service Information, refer to the **Original** Service Manual for Chassis No. P42740-04 and **Notices** for Chassis No. P42740-04 used in Model DP42740 (SM780190).

**SERVICING SHOULD BE PERFORMED BY ONLY TRAINED AND QUALIFIED SERVICE PERSONNEL.**

## 1. IN THE SERVICE ADJUSTMENTS

The are no changes.

## 2. IN THE CHASSIS ELECTRICAL PARTS LIST MISCELLANEOUS

The are no changes.

## 3. PWR ON LED POSITION CHANGE

Before (J4HG): Right side

Current (J4HGE): Left side

For parts or service contact:

**Sanyo Manufacturing Corporation**  
P.O. Box 2000  
3333 Sanyo Road  
Forrest City, Arkansas 72335-2000